






Existing Features

- Restoration Area
- Existing Streams & Ditches
- Hay



Data sources: Base imagery is 2003 NAIP 1M orthophotography. Existing vegetation and hydrography network from 2006 site visits and digitization of existing imagery. Restoration prescriptions by Arrowwood Environmental.

1/09/2007 ...\Projects\Basin\RestorationPlans\2321_1.mxd



Wetland Restoration

- Restoration Area
- Active Corridor Restoration
- Beltwidth Corridor
- Ditch Fill
- Ditchplug
- Restored Stream Channels
- Shrub Swamp
- Floodplain Forest

Lake Champlain Basin Wetland Restoration Plan

Sample Restoration Concept Plan
Site 4963 Shorham, VT